Technical Information



Replaces the Technical Information dated 04.03.04

Update: 07.12.12

KIWOBOND® 1000 HMT

Fast drying, two-component screen adhesive

KIWOBOND 1000 HMT is a fast drying, two-component screen adhesive for a highly chemical resistant bonding of screen meshes to frames made of aluminium, steel, wood and galvanized iron. It is applied by brush and after curing almost completely solvent resistant. KIWOBOND 1000 HMT is fast drying and therefore allows bondings of screen meshes with high tension values without any loss of tension after having released the frame from the stretching unit. The adhesive film does not embrittle and does not cut the mesh if some adhesive has been brushed into the screen surface.

APPLICATION

Before use, thoroughly remove any old adhesive residue from the frame with e.g. PREGAN DL. This is not necessary if the old adhesive film shows an even surface without break-outs. If sand-blasted aluminium frames are used, ensure that the dust is being removed. The bonding areas have to be free from fats and all other materials operating as separating agents. To achieve best adhesion it is recommended in some cases to apply a hardener of the KIWODUR 1000 HMT series onto the frame.

Before use, mix KIWOBOND 1000 HMT with 20% of a hardener of the KIWODUR 1000 HMT series. Stir both components well and apply within approx. 45 - 70 min. Using pressure, apply the adhesive mixture with a hard brush onto the area of the mesh to be bonded. KIWOBOND 1000 HMT dries especially fast, if a relatively thin adhesive film is applied. For very fine meshes (finer than 100 threads/ cm) the mixture can be reduced with a little KIWOSOLV L 63.

The drying time mainly depends on the mesh to be bonded, the quantity of adhesive to be dried and the room temperature in combination with the respective air circulation.

Guide values at 20°C:

Mesh	Time in stretching Unit
100 - 40	approx. 7 min.
51 - 70	approx. 10 min.
21 - 140	approx. 15 min.

While a relatively good resistance to water and many solvents is already achieved after approx. 1 hour, full resistance will only be reached after a total curing time of approx. 24 hours.

Although KIWOBOND 1000 HMT has a very good solvent resistance, it is advisable to protect the adhesive layer with a protective lacquer especially if automatic screen washing units are to be used. ESTELAN Y 224-03 is especially suitable (see separate technical product information). The protective lacquer can be applied after approx. 2 - 3 hours depending on the applied adhesive quantity and drying conditions.

POTLIFE

45 - 70 min. (depending on the room temperature and mixed adhesive quantity)

Technical Information

KIWOBOND® 1000 HMT

Page 2 of 2



update: 07.12.12

REDUCING KIWOSOLV L 63

CLEANING Unhardened: KIWOSOLV L 63

Hardened: PREGAN DL

COLOUR Light red

FLASH POINT Approx. -18°C

HEALTH HAZARDS/ ENVIRONMENTAL PROTECTION When working with KIWOBOND 1000 HMT and a hardener of the KIWODUR 1000 HMT series ensure sufficient ventilation of the working areas. Avoid contact with eyes and skin. Keep away from sources of ignition. Do not

smoke.

Please follow further information given in the material safety data sheets.

STORAGE 2 years at 20 - 25°C and tightly closed original container

At temperatures of approx. + 8°C, KIWOBOND 1000 HMT can become gellike. Warm up to room temperature and shake or stir well to achieve normal consistency. Freezing and warming-up do not have any influence on the

adhesion strength.